



FIN: WDB 907135 1N 006145

Current advice for the vehicle:

none

Outstanding KDM:

Damage code	Description	End date	Campaign state	KDM-Type	Days to Expire
8297010	VS30SIGEBL		Active	Recall	0

ESKULAB decisions:

Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	28.02.2023		55	050930058	VS3LADKOO	1454/SD23	559	06100	515498	km	1	000001004	03.03.2023
	15.02.2022				Service major	1243/2022	559	06100	413195	km			
	22.10.2021				Service minor - Mileage exceeded	8462/2021	559	06100	375404	km			
	25.06.2021		54	054903748	VS3ORTUNKI	5236/SD21	559	06100	329560	km	1	000000918	09.07.2021
	25.06.2021		53	029911537	VS3BREBOL	5236/SD21	559	06100	329560	km	1	000000918	09.07.2021
	25.06.2021				Service minor	5233/2021	559	06100	329560	km			
	22.12.2020	AA	52	000012SV7	Service scope, Service A Service contract	10204SD20	559	06100	294938	km	1	000000904	02.04.2021
	22.12.2020		51	03500NSV7	Rear axle gear oil Service contract	10204SD20	559	06100	294938	km	1	000000904	02.04.2021
	22.12.2020	AB	50	009102SV7	Air filter element Service contract	10204SD20	559	06100	294938	km	1	000000904	02.04.2021
	22.12.2020	AC	49	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	10204SD20	559	06100	294938	km	1	000000904	02.04.2021
	22.12.2020	AD	48	047028SV7	Water separator, fuel system Service contract	10204SD20	559	06100	294938	km	1	000000904	02.04.2021
	22.12.2020		47	043000SV7	Brake fluid change Service contract	10204SD20	559	06100	294938	km	1	000000904	02.04.2021
	22.12.2020				Service minor	10204/202	559	06100	294938	km			
	10.10.2020	AE	46	014001077	Intake manifold/charge air distributor Torn/cracked	8029/SD20	559	06100	263490	km	1	000000886	27.11.2020
	10.10.2020		45	014005068	Stud/screw/nut intake manifold Broken	8029/SD20	559	06100	263490	km	1	000000886	27.11.2020
	10.10.2020		44	009165737	Pressure converter, boost pressure control Electrical fault	8029/SD20	559	06100	263490	km	1	000000886	27.11.2020
	10.10.2020	AE	43	014001M18	Intake manifold/charge air distributor Replacement vehicle	8029/SD20	559	06100	263490	km	1	000000886	27.11.2020
	06.10.2020	AF	42	009175527	Hot film mass air flow meter Does not operate correctly	7900/SD20	559	06100	262148	km	1	000000881	23.10.2020
	06.10.2020	AF	41	009175P18	Hot film mass air flow meter Replacement vehicle	7900/SD20	559	06100	262148	km	1	000000881	23.10.2020
	25.09.2020		40	049048067	Flange connection BTWw. turbocharger and catalytic converter Broken	7583/SD20	559	06100	258848	km	2	000000882	30.10.2020
	25.09.2020	AG	39	000011SV7	Service scope, Service B Service contract	7583/SD20	559	06100	258848	km	1	000000882	30.10.2020

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	25.09.2020	AC	38	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	7583/SD20	559	06100	258848	km	1	000000882	30.10.2020
	25.09.2020				Service major	7583/2020	559	06100	258848	km			
	10.06.2020		37	042960878	VS3BRADVER	4510/SD20	559	06100	218444	km	1	000000867	17.07.2020
	10.06.2020		36	047104527	Valve system, air admission/air release Does not operate correctly	4510/SD20	559	06100	218444	km	1	000000867	17.07.2020
	10.06.2020		35	014502737	NOx sensor downstream of catalytic converter Electrical fault	4510/SD20	559	06100	218444	km	2	000000867	17.07.2020
	10.06.2020	AA	34	000012SV7	Service scope, Service A Service contract	4510/SD20	559	06100	218444	km	1	000000867	17.07.2020
	10.06.2020	AB	33	009102SV7	Air filter element Service contract	4510/SD20	559	06100	218444	km	1	000000867	17.07.2020
	10.06.2020	AC	32	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	4510/SD20	559	06100	218444	km	1	000000867	17.07.2020
	10.06.2020	AD	31	047028SV7	Water separator, fuel system Service contract	4510/SD20	559	06100	218444	km	1	000000867	17.07.2020
	10.06.2020				Service minor - Mileage exceeded	4510/2020	559	06100	218444	km			
	03.04.2020	AH	30	026349F68	Shift rod/shift cable locking element Pops out	2802/SD20	559	06100	194756	km	1	000000856	01.05.2020
	03.04.2020		29	041003D37	Universal joint star Worn out	2802/SD20	559	06100	194756	km	1	000000856	01.05.2020
	03.04.2020	AH	28	026349P18	Shift rod/shift cable locking element Replacement vehicle	2802/SD20	559	06100	194756	km	1	000000856	01.05.2020
	03.04.2020	AH	27	026349P48	Shift rod/shift cable locking element Towing	2802/SD20	559	06100	194756	km	1	000000856	01.05.2020
	06.03.2020		26	035201171	Differential, rear axle Too much play	2060/SD20	559	06100	185295	km	1	000000854	17.04.2020
	06.03.2020		25	050318047	Charge air hose, right, charge air cooler Leaks	2060/SD20	559	06100	185295	km	1	000000854	17.04.2020
	06.03.2020		24	054001537	12 V battery Insufficient effect/power	2060/SD20	559	06100	185295	km	1	000000854	17.04.2020
	06.03.2020		23	082539737	Antenna, radio/automobile telephone, automatic Electrical fault	2060/SD20	559	06100	185295	km	1	000000854	17.04.2020
	06.03.2020		22	054646737	Microswitch, belt warning device Electrical fault	2060/SD20	559	06100	185295	km	1	000000854	17.04.2020
	06.03.2020		21	035311177	Rear axle shaft Too much play	2060/SD20	559	06100	185295	km	1	000000854	17.04.2020
	18.02.2020		20	059N10747	K/Z*, taillamp, right Contact fault/open circuit	1464/SD20	559	06100	177303	km	1	000000851	27.03.2020
	20.01.2020	AG	19	000011SV7	Service scope, Service B Service contract	621/SD20	559	06100	165079	km	1	000000844	07.02.2020
	20.01.2020	AC	18	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	621/SD20	559	06100	165079	km	1	000000844	07.02.2020
	20.01.2020				Service major - Regular service	621/2020	559	26100	165079	km			
	30.12.2019		17	082514737	Function, station selection, radio, head unit Electrical fault	11057SD19	559	06100	159837	km	1	000000842	24.01.2020
	30.12.2019		16	05452E908	SAM control unit, front Software status	11057SD19	559	06100	159837	km	1	000000842	24.01.2020
	30.12.2019		15	033P0B367	Supporting ball joint, right, lower, front axle Noise	11057SD19	559	06100	159837	km	1	000000842	24.01.2020
	30.12.2019		14	046488177	Tie rod ball joint, tie rod, inner, front axle Too much play	11057SD19	559	06100	159837	km	1	000000842	24.01.2020
	30.12.2019		13	046487177	Tie rod ball joint, tie rod, outer, front axle Too much play	11057SD19	559	06100	159837	km	1	000000842	24.01.2020
	30.12.2019		12	072E05048	Foil/insulation, door trim, front door, left Leaks	11057SD19	559	06100	159837	km	1	000000842	24.01.2020



Vehicle Information (Damage history)

52602

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	30.12.2019		11	086003737	Fill level sensor, washer fluid reservoir Electrical fault	11057SD19	559	06100	159837	km	1	000000842	24.01.2020
	01.10.2019	AG	10	000011SV7	Service scope, Service B Service contract	8410/SD19	559	06100	124419	km	0	000000000	11.10.2019
	01.10.2019	AD	9	047028SV7	Water separator, fuel system Service contract	8410/SD19	559	06100	124419	km	0	000000000	11.10.2019
	01.10.2019	AB	8	009102SV7	Air filter element Service contract	8410/SD19	559	06100	124419	km	0	000000000	11.10.2019
	01.10.2019	AC	7	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	8410/SD19	559	06100	124419	km	0	000000000	11.10.2019
	01.10.2019				Service major - Regular service	8410/2019	559	06100	124419	km			
	17.05.2019		6	082920728	VS3VELEBRE	4172/SD19	559	06100	65665	km	0	000000000	24.05.2019
	17.05.2019	AG	5	000011SV7	Service scope, Service B Service contract	4172/SD19	559	06100	65665	km	0	000000000	24.05.2019
	17.05.2019	AC	4	083108SV7	Air/dust combination filter, heating and ventilation system Service contract	4172/SD19	559	06100	65665	km	0	000000000	24.05.2019
	17.05.2019				Service major - Regular service	4172/2019	559	06100	65665	km			
	26.02.2019	AI	3	003201061	Connecting rod Broken	1793/SD19	559	06100	39799	km	0	000000000	12.04.2019
	26.02.2019	AI	2	003201P18	Connecting rod Replacement vehicle	1793/SD19	559	06100	39799	km	0	000000000	12.04.2019
	26.02.2019	AI	1	003201P48	Connecting rod Towing	1793/SD19	559	06100	39799	km	0	000000000	12.04.2019