

Talisman (LFD), 1.6 DCI DIESEL ENGINE, TECNM

VIN: VF1RFD00154711783

License plate: DZ153EH

Equipment: LPA5

Date of manufacture: 2016-01-22

Engine: R9M(452) 118KW

Transmission: DW6(003)

Engine serial number: C034965

History:

Date	Mile(KM)	RC	Complaint	Operation description	OTS no
------	----------	----	-----------	-----------------------	--------

23.01.2023 123559 CLIENT PAYANT A TERME 23.01.2023 (A)

Code (work/parts)	Time/Quantity	Description (work and details)
2633	1ч	SO NoisSrch gearbox assembly
A29L	1.2ч	GO Replace relay bearing
A54U	1.1ч	GO Rem-Ref driveshaft assembly
0145	0.3ч	SO Test vehicle
<u>397740789R</u>	1.00	BRG-INTERMEDIATE
<u>7703066381</u>	1.00	RETAINING RING
<u>397743841R</u>	1.00	BRG-TRANSMISSION,
<u>7711945804</u>	6.00	VALUE + AUTO GB O
<u>383428760R</u>	1.00	SEAL-TRANS OUTPUT
<u>COMPLEMENT</u>	- 1.00	REMISE - 15,00%

23.01.2023 123559 CLIENT AU COMPTANT 23.01.2023 (D)

Code (work/parts)	Time/Quantity	Description (work and details)
<u>REMPCE</u>	1.00	VETUSTE SUITE INT

31.03.2022 112378 CLIENT PAYANT A TERME 31.03.2022 (B)

Code (work/parts)	Time/Quantity	Description (work and details)
8224	1ч	SO Cnty Chk wiring
1999	3ч	SO Repair operation not coded
04NP	1.7ч	SO strp-rbd cylinder head
03XK	2.3ч	SO Rem-Ref timing cover
A050	8ч	GO Rem-Ref engine gearbox assembly
3465	0.3ч	SO AlignAdj front and rear axles
0129	0.5ч	SO Test vehicle
<u>7711945804</u>	3.00	VALUE + AUTO GB O
<u>ITE0004</u>	2.00	ITENET

<u>7711943685</u>	2.00	Renault-Castrol R
<u>7711579085</u>	1.00	JOINT OTS OCHN
<u>7711428129</u>	1.00	COOLANT TYPE D 2L
<u>7711428130</u>	1.00	COOLANT TYPE D 5L
<u>117205040R</u>	1.00	KIT BELT TENSIONE
<u>7701476858</u>	1.00	SEAL
<u>135027147R</u>	1.00	CASE-TIMING
<u>110265505R</u>	1.00	WASHER-CAP SEALIN
<u>8200964242</u>	2.00	NUT-SPINDLE
<u>7703034278</u>	2.00	FLGD HEX NUT PRVL(M12X125-10)
<u>7703034314</u>	2.00	FLGD HEX NUT PRVL
<u>7703102043</u>	1.00	FLGD HEX HD SCR W(M10-40)
<u>147252403R</u>	1.00	DUCT-EXH GAS EXCH
<u>147222354R</u>	1.00	GSKT-EGR INTERCOO
<u>147357086R</u>	1.00	EXCHANGER-BYPASS,
<u>383428760R</u>	1.00	SEAL-TRANS OUTPUT

31.03.2022 112378

CLIENT PAYANT A TERME 31.03.2022
(B)

Code (work/parts)	Time/ Quantity	Description (work and details)
8224	1ч	SO Cnty Chk wiring
1999	3ч	SO Repair operation not coded
04NP	1.7ч	SO strp-rbd cylinder head
03XK	2.3ч	SO Rem-Ref timing cover
A050	8ч	GO Rem-Ref engine gearbox assembly
3465	0.3ч	SO AlignAdj front and rear axles
0129	0.5ч	SO Test vehicle
<u>7711945804</u>	3.00	VALUE + AUTO GB O
<u>ITE0004</u>	2.00	ITENET
<u>7711943685</u>	2.00	Renault-Castrol R
<u>7711579085</u>	1.00	JOINT OTS OCHN
<u>7711428129</u>	1.00	COOLANT TYPE D 2L
<u>7711428130</u>	1.00	COOLANT TYPE D 5L
<u>117205040R</u>	1.00	KIT BELT TENSIONE
<u>7701476858</u>	1.00	SEAL
<u>135027147R</u>	1.00	CASE-TIMING
<u>110265505R</u>	1.00	WASHER-CAP SEALIN
<u>8200964242</u>	2.00	NUT-SPINDLE
<u>7703034278</u>	2.00	FLGD HEX NUT PRVL(M12X125-10)
<u>7703034314</u>	2.00	FLGD HEX NUT PRVL
<u>7703102043</u>	1.00	FLGD HEX HD SCR W(M10-40)
<u>147252403R</u>	1.00	DUCT-EXH GAS EXCH
<u>147222354R</u>	1.00	GSKT-EGR INTERCOO
<u>147357086R</u>	1.00	EXCHANGER-BYPASS,
<u>383428760R</u>	1.00	SEAL-TRANS OUTPUT

07.03.2022 112378

CESSION INTERNE 07.03.2022 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
HCADEP	0ч	CA ISSU DU DEPANNAGE
<u>TE</u>	1.00	NUL
<u>TE</u>	- 1.00	NUL

07.03.2022 112378

CLIENT PAYANT A TERME 07.03.2022
(B)

Code (work/parts)	Time/ Quantity	Description (work and details)
8224	1ч	SO Cnty Chk wiring
1999	3ч	SO Repair operation not coded
04NP	1.7ч	SO strp-rbd cylinder head
03XK	2.3ч	SO Rem-Ref timing cover
A050	8ч	GO Rem-Ref engine gearbox assembly
3465	0.3ч	SO AlignAdj front and rear axles
0129	0.5ч	SO Test vehicle
<u>7711945804</u>	3.00	VALUE + AUTO GB O
<u>ITE0004</u>	2.00	ITENET
<u>7711943685</u>	2.00	Renault-Castrol R
<u>7711579085</u>	1.00	JOINT OTS OCHN
<u>7711428129</u>	1.00	COOLANT TYPE D 2L
<u>7711428130</u>	1.00	COOLANT TYPE D 5L
<u>117205040R</u>	1.00	KIT BELT TENSIONE
<u>7701476858</u>	1.00	SEAL
<u>135027147R</u>	1.00	CASE-TIMING
<u>110265505R</u>	1.00	WASHER-CAP SEALIN
<u>8200964242</u>	2.00	NUT-SPINDLE
<u>7703034278</u>	2.00	FLGD HEX NUT PRVL(M12X125-10)
<u>7703034314</u>	2.00	FLGD HEX NUT PRVL
<u>7703102043</u>	1.00	FLGD HEX HD SCR W(M10-40)
<u>147252403R</u>	1.00	DUCT-EXH GAS EXCH
<u>147222354R</u>	1.00	GSKT-EGR INTERCOO
<u>147357086R</u>	1.00	EXCHANGER-BYPASS,
<u>383428760R</u>	1.00	SEAL-TRANS OUTPUT
<u>COMPLEMENT</u>	- 1.00	

07.03.2022 1

CLIENT PAYANT A TERME 07.03.2022
(A)

Code (work/parts)	Time/ Quantity	Description (work and details)
REMF20K	1ч	FORFAIT 20 KMS ROULE
<u>REMSUP25</u>	1.00	MAJORATION 25%

10.11.2021 103670

CESSION INTERNE 10.11.2021 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
HMOCE	1.2ч	REVISION VEHICULE
HMOCE	0.1ч	REMPL. FILTRE HABITACLE

HMOCE	1.1ч	REPL. LIQUIDE DE REFROIDISEMENT
HMOCE	0.4ч	REPL. KIT ACCESSOIRE
HMOCE	0.6ч	REPL. LIQUIDE DE FREIN
HMOCE	1.5ч	VIDANGE REMPLISSAGE BOITE DE VITESS
HMOCE	0.7ч	REPL. 2 PNEU AV
HMOCE	0.3ч	ESSAI
HMOCE	1.5ч	CONTROLE + REGLAGE GEOMETRIE
HMOCE	0.3ч	REPARATION IMPACT
<u>272774812R</u>	1.00	FLTR-PASS COMPT
<u>110265505R</u>	1.00	WASHER-CAP SEALIN
<u>152093920R</u>	1.00	CRTG-OIL FILTER
<u>MOBV150887</u>	6.80	MOBIL SUPER 3000
<u>117205040R</u>	1.00	KIT BELT TENSIONE
<u>7711575504</u>	1.00	*BRAKE FLUID
<u>152004740R</u>	1.00	FLTR ASSY-OIL, AU
<u>7711579456</u>	7.00	HUILE DE BOITE DW
<u>7711771831</u>	2.00	*TYRES

10.02.2021 87002

CLIENT AU COMPTANT 10.02.2021 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
0145	0.3ч	RKPLC3 FORFAIT DISQUES ET PLAQUETTE - SO Test vehicle
7252	1.2ч	RKPLC3 FORFAIT DISQUES ET PLAQUETTE - GO Repl x2 front brake disc
<u>410606124R</u>	1.00	RKPLC3 FORFAIT DISQUES ET PLAQUETTE - PAD-LINED FR BRAK
<u>402064155R</u>	2.00	RKPLC3 FORFAIT DISQUES ET PLAQUETTE - DISK-FR BRAKE
<u>DM2</u>	1.00	PARTICIP TRAITEME

12.10.2020 82830

INJECTION COMPUTER
(REPROGRAMMING)

0DD2

Code (work/parts)	Time/ Quantity	Description (work and details)
A635	0.1ч	SO Reprogrm special tech operation
7605	0.5ч	SO Applictn special tech operation

10.08.2020 78860

CLIENT AU COMPTANT 10.08.2020 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
3123	1.3ч	RTPLA2 FORFAIT MONTAGE REMPL VALVE - GO D/ReasX4 tyre
<u>7700717645</u>	4.00	RTPLA2 FORFAIT MONTAGE REMPL VALVE - VALVE WHEEL
<u>7711423155</u>	4.00	RTPLA2 FORFAIT MONTAGE REMPL VALVE - W/WGHT 5X9G ADHES
<u>7711655296</u>	4.00	*TYRES

27.07.2020 78860

CLIENT AU COMPTANT 27.07.2020 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
3123	1.3ч	RTPLA2 FORFAIT MONTAGE REMPL VALVE - GO D/ReasX4 tyre
<u>7700717645</u>	4.00	RTPLA2 FORFAIT MONTAGE REMPL VALVE - VALVE WHEEL
<u>7711423155</u>	4.00	RTPLA2 FORFAIT MONTAGE REMPL VALVE - W/WGHT 5X9G ADHES
<u>7711655296</u>	4.00	*TYRES

27.07.2020 78075

OIL CIRCUIT, SEAL INCLUDING
CYLINDER HEAD

Code (work/parts)	Time/ Quantity	Description (work and details)
0230	1.2ч	GO Service vehicle
0145	0.3ч	SO Test vehicle
3592	0.7ч	GO Replace front brake pads
<u>110265505R</u>	000100	WASHER-CAP SEALIN
<u>152093920R</u>	000100	CRTG-OIL FILTER
<u>MOBV150887</u>	000670	MOBIL SUPER 3000
<u>LMD2437</u>	000100	LAVE GLACE CONCEN
<u>410606124R</u>	000100	PAD-LINED FR BRAK

16.03.2020 71395

CLIMATE CONTROL, INCLUDING
CONTROL PANEL

Code (work/parts)	Time/ Quantity	Description (work and details)
0025	0.1ч	SO Replace cabin filter
0228	0.6ч	GO Service vehicle
1440	0.4ч	GO Rem-Ref fuel filter
1102	0.2ч	GO Rem-Ref air filter
0145	0.3ч	SO Test vehicle
6465	1.2ч	GO Replace rear brake pad
<u>272774812R</u>	000100	FLTR-PASS COMPT
<u>LMD2437</u>	000100	LAVE GLACE CONCEN
<u>165571618R</u>	000100	FUEL FILTER
<u>165468296R</u>	000100	AIR FILTER
<u>440608235R</u>	000100	SET RR PAD
<u>288905565R</u>	000100	BLADE-WS WIPER

17.12.2019 65582

ALLUMAGE VOYANT OBD

Témoin OBD : allumé

EGR (EXHAUST GAS RECIRCULATION)

Code (work/parts)	Time/ Quantity	Description (work and details)
A33K	0.2ч	GO Rem-Ref EGR valve
8224	1ч	SO Cnty Chk wiring
0145	0.3ч	SO Test vehicle
<u>147109948R</u>	000100	VALVE COMPL-EGR

11.06.2019 55801

ABSENCE TOTALE OU PARTIELLE
D'AFFICHAG

Informations routières : pas
d'affichage des limitations de
vitesse et zones dan

SOUND, AUDIO EQUIPMENT, DISPLAY,
DVD, SPEAKER

Code (work/parts)	Time/ Quantity	Description (work and details)
-------------------	-------------------	--------------------------------

0311	0.3ч	SO Func Chk computers
001W	0.3ч	SO Confgrtn RADIO

11.06.2019 55801

ABSENCE TOTALE OU PARTIELLE
D'AFFICHAG

Informations routières : pas
d'affichage des limitations de
vitesse et zones dan

SOUND, AUDIO EQUIPMENT, DISPLAY,
DVD, SPEAKER

Code (work/parts)	Time/ Quantity	Description (work and details)
0311	0.3ч	SO Func Chk computers
001W	0.3ч	SO Confgrtn RADIO

30.03.2019 50600

BLOQUE, COMM. SANS
EFFET, N'ENCLENCHE, NE CHARGE
PAS

Appairage bluetooth :
dysfonctionnement de la
connexion du téléphone au
véhicule

SOUND, AUDIO EQUIPMENT, DISPLAY,
DVD, SPEAKER

Code (work/parts)	Time/ Quantity	Description (work and details)
A611	0.4ч	SO Reprogram RADIO
7749	0ч	GO Updating navigation computer
A637	0.4ч	SO Reprogram audio amplifier

30.03.2019 50600

PROGRAM MAINTENANCE

Code (work/parts)	Time/ Quantity	Description (work and details)
-------------------	-------------------	--------------------------------

30.03.2019 50600

ALLUM. VOYANT/MSG SONORE :
AVEC DEFAULT

Alerte de survitesse :
Témoin ou alerte sonore
dysfonctionnement

INSTRUMENT PANEL

Code (work/parts)	Time/ Quantity	Description (work and details)
A4HL	0.3ч	SO Confgrtn instrument panel

30.03.2019 50600

BLOQUE, COMM. SANS
EFFET, N'ENCLENCHE, NE CHARGE
PAS

Appairage bluetooth :
dysfonctionnement de la
connexion du téléphone au
véhicule

SOUND, AUDIO EQUIPMENT, DISPLAY,
DVD, SPEAKER

Code (work/parts)	Time/ Quantity	Description (work and details)
A611	0.4ч	SO Reprogram RADIO
7749	0ч	GO Updating navigation computer
A637	0.4ч	SO Reprogram audio amplifier

20.02.2019 47933

CLIENT AU COMPTANT 20.02.2019 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
3119	0.7ч	LLTLC0 FORFAIT CONTROLE GEOMETRIE T - GO Geom Chk wheel

01.06.2018 31919

BLOQUE, COMM. SANS
EFFET, N'ENCLENCHE, NE CHARGE
PAS

Refroidissement habitacle
avant : dysfonctionnement

CLIMATE CONTROL, INCLUDING
CONTROL PANEL

Code (work/parts)	Time/ Quantity	Description (work and details)
6959	2ч	SO Rem-Ref condenser
6067	0.6ч	SO SealChk refrigerant circuit
6066	0.9ч	GO Drn-Refl refrigerant circuit
0145	0.3ч	SO Test vehicle
8201472341	000100	COLL CAP CA 1234Y

<u>924750001R</u>	000100	KIT SEAL AC SYSTE
<u>921001829R</u>	000100	CONDENSER

11.05.2018 29203

BLOQUE, COMM. SANS
EFFET, N'ENCLENCHE, NE CHARGE
PAS

Refroidissement habitacle
avant : dysfonctionnement

CLIMATE CONTROL, INCLUDING
CONTROL PANEL

Code (work/parts)	Time/ Quantity	Description (work and details)
6066	0.9ч	GO Drn-Refl refrigerant circuit
0145	0.3ч	SO Test vehicle
6067	0.6ч	SO SealChk refrigerant circuit
A52T	0.8ч	SO Rem-Ref pp bet int pp ac comp
<u>CM</u>	000100	HFO-1234YF FILL
<u>L5</u>	000100	AIR CONDITIONING OIL, COMBUSTION ENGINE VEHICLE
<u>924750001R</u>	000100	KIT SEAL AC SYSTE

19.04.2018 26940

INJECTION COMPUTER
(REPROGRAMMING)

0CQX

Code (work/parts)	Time/ Quantity	Description (work and details)
0095	0.1ч	SO Applictn special tech operation
7605	0.5ч	SO Applictn special tech operation

19.04.2018 26940

CESSION INTERNE 19.04.2018 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
0025	0.1ч	SO Replace cabin filter
0230	1.2ч	GO Service vehicle
1999	0.7ч	SO Repair operation not coded
0145	0.3ч	SO Test vehicle
<u>7711421790</u>	1.00	COFFRET LAMPE LAG
<u>8201599663</u>	1.00	COLLECTION MAT FL
<u>7711239101</u>	1.00	ANTITHEFT SCREW J
<u>8671093116</u>	2.00	MOTRIO PREMIUM OI
<u>7711238971</u>	1.00	SCREENWASH 500ML
<u>272774812R</u>	1.00	FLTR-PASS COMPT
<u>152093920R</u>	1.00	CRTG-OIL FILTER
<u>7703062062</u>	1.00	RING SEAL16
<u>7711782054</u>	1.00	RENAULT BAG BLACK
<u>7711419386</u>	1.00	FIRE EXT 1 KG NLA
<u>7711780762</u>	1.00	KIT 2 EN 1 TRIANG

22.11.2017 26978

DEMARRAGE DIFFICILE: A CHAUD

Démarrage du moteur :
impossible

FRONT SHOCK ABSORBERS

Code (work/parts)	Time/ Quantity	Description (work and details)
00C9	1.4ч	SO Rem-Ref front shock absorber
A39R	1.1ч	SO Geom Chk front and rear axles
<u>7703602222</u>	000200	FLGD HEX HD SCR W
<u>7703034306</u>	000100	PREVAILING TORQUE
<u>543207020R</u>	000100	UNIT-FILTERING AS

<u>543258271R</u>	000100	STOP-ROTARY
<u>540505177R</u>	000100	STOP-BUMP FR
<u>540303710R</u>	000100	SUPT-FR SPR, LWR
<u>543029696R</u>	000100	ABS-SHOCK, FR

22.11.2017 26978 COGNE,CLAQUE,CRAQUE,CLAPOTE particulière : passage de trottoir, ralentisseur

Bruit/Vibration sur route

FRONT AND REAR AXLES, EXCEPT SHOCK ABSORBER AND BEARING

Code (work/parts)	Time/Quantity	Description (work and details)
A3I3	0.5ч	GO RemRefx2 fr anti-roll br tie-rod
3029	1.5ч	SO NoisSrch front and rear axles
<u>7703034247</u>	000400	H NUT W/FLNG PRVL
<u>546182227R</u>	000200	ROD-ANTIROLL BAR

22.11.2017 26978

CESSION INTERNE 22.11.2017 (B)

Code (work/parts)	Time/Quantity	Description (work and details)
<u>CARBCLT</u>	1.00	CARBURANT CLIENT

20.10.2017 26978

CESSION INTERNE 20.10.2017 (A)

Code (work/parts)	Time/Quantity	Description (work and details)
9499	0.5ч	SO Repair operation not coded
<u>IP</u>	0.50	ING PEINTURE NACR

16.10.2017 26978

SEATS, FRAMES, SUB-FRAME

0CBM

Code (work/parts)	Time/Quantity	Description (work and details)
7603	0.3ч	SO Applctn special tech operation

16.10.2017 26978

DASH BOARD,STEERING WHEEL,ADJUSTMENT

0CFB

Code (work/parts)	Time/Quantity	Description (work and details)
0095	0.1ч	SO Applctn special tech operation
7602	0.2ч	SO Applctn special tech operation
<u>7703077117</u>	000200	CLIP

16.10.2017 26978 DEMARRAGE DIFFICILE: A CHAUD

Démarrage du moteur : impossible

BATTERY

Code (work/parts)	Time/Quantity	Description (work and details)
8205	0.2ч	GO Rem-Ref 12 V battery
8217	0.1ч	SO Check 12 V battery
<u>7711575175</u>	000100	BATTERY

16.10.2017 26978

CESSION INTERNE 16.10.2017 (C)

Code (work/parts)	Time/Quantity	Description (work and details)
0048	1.3ч	GO Service vehicle

1999	0.5ч	SO Repair operation not coded
1999	0.8ч	SO Repair operation not coded
<u>963737470R</u>	1.00	SHELL-OTR LH MIRR
<u>963664523R</u>	1.00	GLASS-OTR LH MIRR
<u>963317848R</u>	1.00	MIRROR- LH OTR AD
<u>7701383038</u>	4.00	TRX 80W/140 0.5L
<u>7703062062</u>	1.00	RING SEAL16
<u>272775114R</u>	1.00	CARBON CABIN FILTER
<u>8660003043</u>	1.00	OIL FILTER
<u>7711220016</u>	2.00	CR2032 BATTERY X1

08.08.2016 14050

CLIENT AU COMPTANT 08.08.2016 (A)

Code (work/parts)	Time/ Quantity	Description (work and details)
4999	2ч	SO Repair operation not coded
9999	2.5ч	SO Replace mscyl hyd unt rg brk pp
IP	1.00	MATERIAL PINTURA

29.03.2016 780

DUR(E).DIFF.A MANOEUVRER,A
VERROUILLER

Ouvrant arrière : ouverture
difficile ou impossible

MECHANISMS-LOCKS

Code (work/parts)	Time/ Quantity	Description (work and details)
5424	0.5ч	SO Rem-Ref rr side op el lock
7006	0.3ч	GO Rem-Ref rr side op el trim
<u>825039922R</u>	000100	LOCK-RR LH DOOR
<u>806206727R</u>	000100	CABLE-CONT, FR DO
<u>825062112R</u>	000100	CABLE-CONT, RR DO

29.03.2016 780

BRAKING, HYDRAULIC AND POWER
ASSISTED

0C97

Code (work/parts)	Time/ Quantity	Description (work and details)
0095	0.1ч	SO Applictn special tech operation
7606	0.6ч	SO Applictn special tech operation
<u>7703085037</u>	000300	STRIP-TIGHTENING
<u>7703085037</u>	000100	STRIP-TIGHTENING

11.03.2016 1

SEATS, FRAMES, SUB-FRAME

0C98

Code (work/parts)	Time/ Quantity	Description (work and details)
0095	0.1ч	SO Applictn special tech operation
7605	0.5ч	SO Applictn special tech operation
<u>883303028R</u>	000100	COVER KIT-2ND ROW